

# Quick operation Guide

V 2.1



# Snoppa Go

<b>Function</b>	<b>Gimbal status</b>	<b>Operation</b>
Battery Check	Power off	press P
Switch on gimbal	Power off	press P + press & hold P
Switch off gimbal	Power on	press & hold P
Sleep/wakeup	Power on	press P
Switch working modes	Power on	press joystick
LED light switch	Power on	press & hold joystick
Gimbal re-calibration	Sleep	press P for 4 times and keep still
Power supply to GoPro	Power on	press P for 3 times quickly